

A photograph showing a section of a cobblestone-paved area. A circular pattern of cobblestones is visible on the left, bordered by a red brick curb. A silver car is parked on the right side of the frame. The cobblestones are irregular in shape and color, ranging from light to dark grey. The red brick curb is made of rectangular bricks laid in a running bond pattern. The overall scene is outdoors, with shadows cast across the pavement.



A close-up photograph of a cobblestone pavement. The stones are dark grey and rectangular, arranged in a regular pattern. A metal manhole cover is visible on the right side of the image. The cover is circular with a grid pattern and is surrounded by lighter-colored cobblestones. A concrete curb separates the dark grey stones from the lighter ones.



A photograph showing a close-up view of a cobblestone pavement. The stones are irregularly shaped and laid in a pattern. A yellow-painted curb runs along the edge of the pavement.

A photograph of a building entrance. The door is made of dark wood with a grid pattern of small squares. To the right of the door is a small white rectangular light fixture mounted on the wall. The ground in front of the door is paved with dark cobblestones. A long shadow is cast across the cobblestones from the left.

A close-up photograph of a cobblestone pavement. A large, irregularly shaped, light-colored patch, possibly a repair or stain, is visible on the right side of the image. The patch has a rough, textured appearance. The surrounding cobblestones are dark and wet. In the background, a brick wall and a doorway are visible.